

Distances from SNWA Points of Diversion to Regional Springs in White River and Pahrnagat Valleys

Straight Line to Springs				
Point of Diversion	Application #	Ash Spring	Crystal Spring	Hiko Spring
Delamar 6 CFS	53991	15.8 miles	17.0 miles	16.5 miles
Delamar 10 CFS	53992	21.8 miles	24.8 miles	25.6 miles
Dry Lake 6 CFS	53989	26.7 miles	25.2 miles	22.1 miles
Dry Lake 10 CFS	53990	34.4 miles	33.4 miles	30.3 miles

West Along Fault and South to Springs				
Point of Diversion	Application #	Ash Spring	Crystal Spring	Hiko Spring
Delamar 6 CFS	53991	27.8 miles	25.8 miles	22.8 miles
Delamar 10 CFS	53992	38.7 miles	36.7 miles	33.7 miles
Dry Lake 6 CFS	53989	33.3 miles	31.3 miles	28.2 miles
Dry Lake 10 CFS	53990	39.2 miles	37.2 miles	34.1 miles

Straight Line to Springs					
Point of Diversion	Application #	Hot Creek	Moon River	Butterfield	Flag
Cave 6 CFS	53987	14.2 miles	15.7 miles	8.3 miles	8.2 miles
Cave 10 CFS	53988	14.5 miles	16.7 miles	6.2 miles	7.0 miles

North to Fault then SW to Springs					
Point of Diversion	Application #	Hot Creek	Moon River	Butterfield	Flag
Cave 6 CFS PoD	53987	42.5 miles	45.2 miles	33.2 miles	34.6 miles
Cave 10 CFS PoD	53988	37.0 miles	39.7 miles	28.3 miles	29.6 miles