## DEC 5 1980

## WATER RIGHTS

Application No. 5/599 (18-40) REPORT OF WELL DRILLER rded: B. C..... T. B..... STATE OF UTAH Claim No .... Coordinate No ... GENERAL STATEMENT: Report of well driller is hereby made and filed with the State Engineer, in accordance with the laws of Utah. (This report shall be filed with the State Engineer within 80 days after the completion or abandonment of the well. Failure to file such reports constitutes a misdemeanor.) Drawdown is the distance in feet the water level is low-ered below static level. (12) WELL TESTS: (1) WELL OWNER: Nam Corp. of the Pres. of the Aaronic Orde Address Box 7095 Murray, Utah 84107 Was a pump test made? Yes [] No E If so, by whom?... Yield: gal./min. with feet drawdown after.... (2) LOCATION OF WELL: County Millard Ground Water Basin (leeve blank) Bailer test gal./min. with feet drawdown after... feet from SE Corn 1026 Temperature of water 540 F. Was a chemical analysis made? No 🗓 Yes 🗆 # SLBM (strike (13) WELL LOG: Diameter of well 16" of Section 10 \_\_\_\_\_, T\_\_20 feet. Depth of completed well 110 feet. Depth drilled 110 out words not needed) NOTE: Place an "X" in the space or combination of spaces needed to designate the material or combination of materials encountered in each depth interval. Under REMARKS make any desirable notes as to occurrence of water and the color, size, nature, etc., of material encountered in each depth interval. Use additional sheet if needed. (3) NATURE OF WORK (check): New Well DX Replacement Well [ Decpening [ Repair [ Abandon [ If abandonment, describe material and procedure: MATERIAL REMARKS Conglomer (4) NATURE OF USE (check): Clay Silk Gravel Industrial [] Municipal 🔲 Mining [ Other 🔲 Test Well 0 (5) TYPE OF CONSTRUCTION (check): 40 Dug 🗆 40 43 43 75 77 x x (6) CASING SCHEDULE: Threaded | | Welfed | | 100 16 " Diam. from 0 feet to 110 fe 110 New 🚡 Reject [] (7) PERFORATIONS: Perforated? Yes 20 No D Size of perforations 5/16 ...perforations from \_\_\_perforations from perforations from... (8) SCREENS: Well screen installed? Yes | No & Madel No. Ret from. Slot size.... (9) CONSTRUCTION: Was well gravel packed? Yes □ No E Size of gravel:..... Was a surface seal provided? Yes 🔲 No 🗀 Did any strata contain unusable water? Yes .... Depth of strata... Work started 8-1 1979. Completed 10-15 Method of sealing strate off:...... (14) PUMP: Manufacturer's Name. Was surface casing used? W.P. Was it comented in place? Yes Depth to pump or bowles feet (10) WATER LEVELS: Well Driller's Statement: Static level 21 feet below land surface Date 10-15-79 This well was drilled under my supervision, and this report is true to the best of my knowledge and belief. Artesian pressure .......feet above land surface Date... Name Scott L. Anderson (Type or print) LOG RECEIVED: (11) FLOWING WELL: (Person, firm, or corporation Address EskDale, Utah 84728 (Signed) Last F. Fusierson Valve 🔲 Controlled by (check) Cap 🗆 Plug 🗀 No Control [ License No. 391 Date 10-15-79 Does well look around casing? . 1979

m 113-534-12-60