


Appendix A. Photographs of Continual-Recording Streamflow Gages, Great Basin National Park Area, Nevada

This page left intentionally blank



PHOTOGRAPH BY DAVID A. BECK, U.S. GEOLOGICAL SURVEY

A. Looking downstream (northeast), October 2002.



PHOTOGRAPH BY GRETCHEN BAKER, NATIONAL PARK SERVICE

B. Looking downstream, January 2003.


Photographs A1. Strawberry Creek above park boundary, Great Basin National Park, Nevada.



PHOTOGRAPH BY DAVID A. BECK, U.S. GEOLOGICAL SURVEY

C. Looking downstream, June 2003.

Photographs A1.—Continued.



PHOTOGRAPH BY DAVID A. BECK, U.S. GEOLOGICAL SURVEY

A. Looking upstream (east), October 2002.

Photographs A2. Shingle Creek near park boundary near Osceola, Nevada.



PHOTOGRAPH BY DAVID A. BECK, U.S. GEOLOGICAL SURVEY

B. Looking upstream, January 2003.



PHOTOGRAPH BY DAVID A. BECK, U.S. GEOLOGICAL SURVEY


C. Looking upstream, June 2003.

Photographs A2.—Continued.



PHOTOGRAPH BY DAVID A. BECK, U.S. GEOLOGICAL SURVEY

A. Looking upstream (northwest), September 2002.



PHOTOGRAPH BY DAVID A. BECK, U.S. GEOLOGICAL SURVEY

B. Looking upstream, June 2003.

Photographs A3. Lehman Creek near Baker, Nevada.



PHOTOGRAPH BY DAVID A. BECK, U.S. GEOLOGICAL SURVEY

A. Looking south, October 2002.



PHOTOGRAPH BY DAVID A. BECK, U.S. GEOLOGICAL SURVEY

B. Looking upstream (west), July 2003.

Photographs A4. Rowland Spring at park boundary near Baker, Nevada.



PHOTOGRAPH BY DAVID A. BECK, U.S. GEOLOGICAL SURVEY

C. Looking downstream (east), September 2002.

Photographs A4.—Continued.



PHOTOGRAPH BY DAVID A. BECK, U.S. GEOLOGICAL SURVEY

A. Looking upstream (west), October 2002.

Photographs A5. Baker Creek at the Narrows, near Baker, Nevada.



PHOTOGRAPH BY DAVID A. BECK, U.S. GEOLOGICAL SURVEY

B. Looking upstream, January 2003.



PHOTOGRAPH BY DAVID A. BECK, U.S. GEOLOGICAL SURVEY


C. Looking upstream, June 2003.

Photographs A5.—Continued.



PHOTOGRAPH BY DAVID A. BECK, U.S. GEOLOGICAL SURVEY

A. Looking downstream (east), October 2002.



PHOTOGRAPH BY DAVID A. BECK, U.S. GEOLOGICAL SURVEY

B. Looking downstream, January 2003.

Photographs A6. Snake Creek above pipeline, Great Basin National Park, Nevada.



PHOTOGRAPH BY DAVID A. BECK, U.S. GEOLOGICAL SURVEY

A. Looking upstream (west), October 2002.



PHOTOGRAPH BY DAVID A. BECK, U.S. GEOLOGICAL SURVEY

B. Looking upstream, January 2003.

Photographs A7. Snake Creek at park boundary near Baker, Nevada.



PHOTOGRAPH BY DAVID A. BECK, U.S. GEOLOGICAL SURVEY

C. Looking upstream, June 2003.

Photographs A7.—Continued.



PHOTOGRAPH BY DAVID A. BECK, U.S. GEOLOGICAL SURVEY

A. Looking upstream (west), January 2003.

Photographs A8. Snake Creek below confluence with Spring Creek near Garrison, Utah.



PHOTOGRAPH BY DAVID A. BECK, U.S. GEOLOGICAL SURVEY

B. Looking upstream, June 2003.

Photographs A8.—Continued.



PHOTOGRAPH BY DAVID A. BECK, U.S. GEOLOGICAL SURVEY

A. Looking upstream (west), January 2003.

Photographs A9. Snake Creek at Nevada–Utah State line near Garrison, Utah.



PHOTOGRAPH BY DAVID A. BECK, U.S. GEOLOGICAL SURVEY

B. Looking downstream (east), January 2003.



PHOTOGRAPH BY GRETCHEN BAKER, NATIONAL PARK SERVICE

C. Looking upstream (west), February 2004.

Photographs A9.—Continued.



PHOTOGRAPH BY DAVID A. BECK, U.S. GEOLOGICAL SURVEY


A. Looking upstream (west), October 2002.



PHOTOGRAPH BY WILLIAM VAN LIEW, NATIONAL PARK SERVICE

B. Looking upstream, June 2003.

Photographs A10. South Fork Big Wash above park boundary near Baker, Nevada.



PHOTOGRAPH BY DAVID A. BECK, U.S. GEOLOGICAL SURVEY

A. Looking upstream (east), October 2002.



PHOTOGRAPH BY DAVID A. BECK, U.S. GEOLOGICAL SURVEY

B. Looking downstream (west), October 2002.

Photographs A11. Williams Canyon above aqueduct near Minerva, Nevada.



PHOTOGRAPH BY DAVID A. BECK, U.S. GEOLOGICAL SURVEY

A. Looking upstream (north), October 2002.



PHOTOGRAPH BY DAVID A. BECK, U.S. GEOLOGICAL SURVEY

B. Looking downstream (south), October 2002.

Photographs A12. Decathon Canyon below park boundary near Minerva, Nevada.

This page left intentionally blank